

RFQ NUMBER : 2492300171

DATE : 10.03.2023

REQ No : 1172300077

REQ TITLE : Supply,install 1172300077

DELIVERY LOCATION

CLOSING DATE : 16.03.2023

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
1	700000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE FREE STANDING SPLIT AC UNIT. 5 TR AT MRDF 132 KV SS 132 KV GIS ROOM AN D TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 175144 SAP EQPT NO.: 30349084)	1	EA				
2	700000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE FREE STANDING SPLIT AC UNIT. 5 TR AT MRDF 132 KV SS 132 KV GIS ROOM AN D TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE	1	EA				



RFQ NUMBER : 2492300171

DATE : 10.03.2023

REQ No : 1172300077

REQ TITLE : Supply,install 1172300077

DELIVERY LOCATION

CLOSING DATE : 16.03.2023

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 175146 SAP EQPT NO.: 30349086)						
3	700000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE FREE STANDING SPLIT AC UNIT. 5 TR AT ODMT 132 KV SS 132 KV GIS ROOM AN D TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING THE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 175469 SAP EQPT NO.: 30349258)		EA				
4	700000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE FREE STANDING SPLIT AC UNIT. 5 TR AT HRSR 400 KV SS FIRE PUMP ROOM AND		EA				



RFQ NUMBER : 2492300171

DATE : 10.03.2023

REQ No : 1172300077

REQ TITLE : Supply,install 1172300077

DELIVERY LOCATION

CLOSING DATE : 16.03.2023

CLOSING TIME : 10:00:00

SL NO	ITEM CODE	SERVICE ID	DESCRIPTION	QTY	UOM	BRAND/ORIGIN	WARRANTY	UNIT PRICE	TOTAL PRICE
			TO REPLACE EXISTING DEFECTIVE SPLIT AC UNIT AS PER THE ATTACHED SPECIFICATION. THE CONTRACTOR IS ALSO RESPONSIBLE FOR DISMANTLING T HE DEFECTIVE SPLIT AC UNIT FROM THE RESPECTIVE SUBSTATION AND TO SCRAP IT AT DEWA CENTRAL STORES SCRAP YARD AT RUWAYYA (EXISTING AC UNIT ASSET NUMBER: 121000004635 SAP EQPT NO.: 30348769)						
5	700000011		SUPPLY, INSTALLATION, TESTING AND COMMISSIONING OF DECORATIVE FREE STANDING SPLIT AC UNIT. 5 TR AT WRSN 400 KV SS LVAC ROOM	1	EA				

TOTAL AMOUNT IN WORDS: TOTAL AMOUNT:

SPECIAL NOTES / INSTRUCTIONS:

Supply,install

STANDARD TERMS & CONDITIONS



RFQ NUMBER : 2492300171

DATE : 10.03.2023

REQ No : 1172300077

REQ TITLE : Supply,install 1172300077

DELIVERY LOCATION

CLOSING DATE : 16.03.2023

CLOSING TIME : 10:00:00

- 1) Prices should be 'DDP' delivery duty paid at DEWA stores.
- 2) Quotation to be submitted only in local currency U.A.E Dirhams
- 3) DEWA Standard payment terms is '30 days credit' from the date of acceptance of material
- 4) No DEWA staff or his or her relatives up to third degree should have ownership or partnership in your company, and your participation in DEWA tenders / RFQs should not constitute a Conflict or perceived Conflict of Interest.
- 5) The offered product and/ or services in the Quotation, shall be conforming and in accordance with DEWA Energy Management Policy & EnMS Manual.

SUPPLIER'S REMARKS:

SUPPLIER'S SIGNATURE AND STAMP